



AGGREGATE FOR BASE FIELD SECTION 1007

1007.1 SCOPE. To establish procedures for the inspection and acceptance of aggregate for base.

1007.2 PROCEDURE. Inspection, testing, and sampling will be governed by the instructions contained in [Field Sec 1001](#) of this Manual.

1007.2.1 Field tests required are as follows:

- (a) Sieve analysis.
- (b) Percent deleterious substances .
- (c) Plasticity index.

1007.2.2 Samples required for Laboratory tests are as follows :

- (a) Initial Approval.
- (b) Production samples at the discretion of the District .

1007.3 ACCEPTANCE. Acceptance is based on routine tests in the field to insure compliance with Specification Sec 1007.

1007.4 RECORDS AND REPORTS. All plant records shown in Field Sec 1001.6 of this Manual shall be maintained. A sample record of aggregate inspection shall be created in SiteManager in accordance with Automation Section 3510 of this Manual.

