



AGGREGATE FOR SEAL COATS FIELD SECTION 1003

1003.1 SCOPE. To establish procedures for the inspection and acceptance of aggregates for use in seal coats.

1003.2 PROCEDURE. Inspection, testing and sampling will be governed by the instructions contained in [Field Sec 1001](#) of this Manual.

1003.2.1 Field tests required are as follows:

- (a) Sieve analysis.
- (b) Percent deleterious substances.

1003.2.2 Samples required for Laboratory tests are as follows:

- (a) Initial approval.
- (b) Production samples at the discretion of the District.

1003.3 ACCEPTANCE. Acceptance is based on routine tests in the field, to insure compliance with Specification Sec 1003.

1003.4 RECORDS AND REPORTS. All plant records shown in Field Sec 1001.6 of this Manual shall be maintained. The aggregates shall be reported through SiteManager in accordance with Automation Section AS-3510 of this Manual.